CALIFORNIA DEPARTMENT OF FISH AND GAME STREAM SURVEY FILE FORM No


NAME SAWYER CRE	SEK	COUNTY Mendocino
STREAM SECTION	FROM mouth	TO First meadow 1 mi.LENGTH 1 mi.
		upstream
TRIBUTARY TO Bott	com Creek	TWP 16N R 15W SEC 36
OTHER NAMES None	2	RIVER SYSTEM Navarro River
SOURCES OF DATA	Personal observation and I	Masonite foresters.


~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~			
EXTENT OF OBSERVATION			
Include Name of Surveyor, Date, Etc.	EXTENT OF OBSERVATION - Sawyer Creek was surveyed on July 16, 1962		
LOCATION RELATION TO OTHER WATERS GENERAL DESCRIPTION	by John Rowell and Herbert Adams. This was done by driving along		
Watershed Immediate Drainage Basin	the stream with frequent stops for closer inspection.		
Altitude (Range) Gradient	LOCATION -		
Width Depth			
Flow (Range) Velocity			
Bottom Spawning Areas			
Pools Shelter			
Barriers Diversions	RELATION TO OTHER WATERS - This is a minor headwater tributary		
Temperatures Food	which contributes winter flows only.		
Aquatic Plants Water Conditions	GENERAL DESCRIPTION - Watershed & Immediate Drainage Basin -This		
Pollution Springs	stream is within the coastal redwood belt. The soil is light grey		
FISHES PRESENT AND SUCCESS OTHER VERTEBRATES	powder with some gravel mixed in. Sawyer Creek flows in a general		
FISHING INTENSITY OTHER RECREATIONAL USE	southeast direction and drains approximately 1½ square miles. This		
ACCESSIBILITY OWNERSHIP	is a steep V-shaped canyon. Redwood and beech trees are		
POSTED OR OPEN IMPROVEMENTS	predominant, providing abundant shade. The area surrounding Sawyer		
PAST STOCKING GENERAL ESTIMATE	Creek has been logged in the past.		
RECOMMENDED MANAGEMENT SKETCH MAP	Altitude - Sawyer Creek arises at 1200 ft, above sea level,		
REFERENCES AND MAPS	dropping to 560 ft. at the mouth.		
	<u>Gradient</u> - Steep in the upper half, dropping 500 ft. within a half		
mile, slight in the lower section, dropping only 150 ft, per mile.			
<u>Width</u> - Riffles were pretty constant at 1½ ft. Pools were about 3 ft.			
<u>Depth</u> - Riffles were only 2 inches, while the pools were about 10 in, to 12 inches.			
Flow - Intermittent with less than 1/2 cfs at time of survey.			
<u>Velocity</u> - Slow.			
	lt and gravel throughout surveyed section.		
Spawning Areas - Only about 10% of the surveyed section looked okay for steelhead			
spawning,			
Pools - Pools formed about 50% of the stream. They were rectangular in shape,			
approximately 3' x 5'.			
Shelter - Most of the shelter was from overhanging logs and trees,			
Barriers - None.			
Diversions - None.			
Temperatures - Taken at 1300, the air registered 95° F., water 65° F.			
Food - Not observed.			
Aquatic Plants - Algae to some extent.			
<u>Winter Conditions</u> - Apparently not too severe. Rainfall figures for this area were			
not available at the time of the survey.			
Pollution - None.			
Springs - None observed.			
FISHES PRESENT AND SUCCESS - None observed.			
OTHER VERTEBRATES - Frogs and snakes.			

SAWYER CREEK Mendocino County

FISHING INTENSITY - None. OTHER RECREATIONAL USES - None. ACCESSIBILITY - A road parallels Sawyer Creek from the mouth for 1 mile upstream. It is reached by turning off the Masonite road at mile 27, then driving 1½ miles up the Little North Fork to road H-2. .4 mile up H-2 is the Sawyer Creek road travel time approximately 1 hour from Ukiah. OWNERSHIP - Union Lumber Company. POSTED OR OPEN - Posted. IMPROVEMENTS - None appear to be needed. PAST STOCKING - None known. GENERAL ESTIMATE - The area that would be attractive to steelhead is rather short. This steep V-shaped canyon has a great many trees, lying across the stream but not touching the bottom. These trees were pushed over when the paralleling road was built. The gravel bottom seems to be alright for steelhead spawning although no fish were observed. The flows are intermittent. RECOMMENDED MANAGEMENT - This stream is not suitable for steelhead and/or rainbow trout or silver salmon in its present condition* It is doubtful if this small tributary will ever be suitable for fish life in the near future. The amount of silt and its proximity to the road are the main hazards involved. SKETCH MAP - See attached. REFERENCES AND MAPS - U.S. Dept. of Interior geological survey 15-minute series topographic map, Booneville quadrangle 1959; Masonite Corp. property and topographic maps based on War Dept. maps 1943.

John Rowell/cd 9-5-62





SPOONER CR. - 30 %. BOTTOM CR. - 10 %.