
FISH HABITAT IMPROVEMENT COMPLETION FORM REGION 3

Stream or Lake Name <u>Horse Creek</u> Tributary to <u>Rancheria Creek</u>
County Mendocino Township 13N Range 15W Section 2&3 ½S
Section of stream work One mile upstream from confluence with Rancheria Creek
Sponsor Fish and Game Work crew New Growth Forestry
Landowner name, address, phone # Congaree River Limited (Western Timber Services)
P.O. Box 1136 Arcata, CA 95521 and Harry Merlo 11 SW Fifth Ave., Ste. 4200. Portland OR 97204
Project duration Dec 1986 - Jan 1987 Man-days expended (dates)
Source of funding SB400 Total cost
Project benefitFish passage Species affected SH
Number of jams removed 10 Number that were barriers 4
Cubic yards of material removedAmount of sediment
Miles of stream opened 1½2 Miles improved
Methods used Hand labor, chainsaws - burn material
Further action recommended
Location of maps and photos
Additional comments, explanations, or details:



HORSE CREEK SITE DESCIPTIONS

- Site 1. Debris jam, 60'x20'x8', not a barrier. Causing side bank erosion and bringing down adjacent trees. Widen channel and burn.
- Site 2. Partial barrier, 25'x25'x7', at confluence of two main branches. Full remove and burn.

Take love-leave big staff

Site 3. Partial barrier, completely embedment of 8' of gravel. Partial removal and burn.

Stay & Center Make it drop

- Site 4. Waterfall. Minor removal of debris from channel to lower jump slightly and remve obstructions.
- Site 5. Debris jam, not a barrier, in narrow section of creek. Clear a channel for debris flushing from above. Burn.
- Site 6. Debris jam behind old Humboldt crossing, not a barrier. Clear a channel to one side.
- Site 7. 5' waterfall and downstream debris pile. Remove obstructing pieces from the spillway and reduce height of fall as necessary. Remove downstream debris.
- Site 8. Partial barrier impounding 15'-20' of bedload. Clear a channel and burn.
- Site 9. Debris jam, not a barrier, with active slides from each bank. Clear a channel and burn.

Minimal removal - Don't increase aromen

- Site 10. Debris jam, not a barrier, impounding 6' of bedload. Clear a channel for low flow passage.
- Site 11. Complete barrier, no fish above. Clear a channel and burn.
- Site 12. Debris jam. Clear center of channel.
- Site 13. 4' fall over rock and debris. Remove debris.
- Site 14. 4' fall over rock. Remove adjoining log to lower and clear jump.
- Site 15. 4' fall. Lower jump.
- Site 16. 5' drop over bedrock formation. Blasting may be necessary.
- Site 17. Debris jam, not a barrier. Clear a channel.
- Site 18. Partial barrier impounding 4^{\prime} of bedload. Clear a channel.