

Date: July 1, 1985

FISH HABITAT IMPROVEMENT COMPLETION FORM  
REGION 3

Stream or Lake Name Brush Creek Tributary to Pacific Ocean

County Mendocino Township 13N Range 16W Sec 26 1/4s

Section of stream worked as marked on the attached map.

Sponsor Calif. Dept. of Fish and Game Work crew DFG

Landowner name, address, phone # \_\_\_\_\_

Project duration 7/20/84 Man-days expended 3  
(dates)

Source of funding DJ603 Total cost \_\_\_\_\_

Project benefit fish passage Species effected SS, SH

Number of jams removed 1 Number that were barriers 1

Cubic yards of material removed 8 Amount of sediment none

Miles of stream opened 4 Miles improved \_\_\_\_\_

Methods used cobra drill and blasting

Further action recommended follow-up inspection

Location of maps and photos attached and U.S.G.S. Pt. Arena 15' photos in DJ slide show

Additional comments, explanations, or details:

A large boulder caught in a bedrock narrows was trapping logs and logging slash creating an absolute barrier to salmon and steelhead migration. CEMR removed the wood material using boom trucks from the existing logging road.

DFG blasted the boulder to prevent the jam from reforming.

CEMR is presently doing extensive log jam barrier removal both upstream and downstream of this project site.

X-LOCATION OF WORK SITE

U.S.G.S. 7T. ARONA  
151

STATE OF CALIFORNIA  
DEPARTMENT OF WATER RESOURCES

