

FISH HABITAT IMPROVEMENT COMPLETION FORM

REGION 3

Stream or Lake Name Ten Mile River (S.F.) Tributary to Pacific Ocean

County Mendocino Township 19N Range 16W Section 11 1/4S

Section of stream worked _____ as marked on the attached map

Sponsor Calif. Dept. Fish & Game Work Crew C.E.M.R.

Landowner name, address, phone # Georgia Pacific Co. - Mr. A. J. Gray,
90 W. Redwood Ave. (707) 964-5651

Project duration June 1984 Man-days expended _____
(dates)

Source of funding DJ 604-3 Total Cost _____

Project benefit fish passage Species affected SS,SH

Number of jams removed 1 Number that were barriers 0

Cubic yards of material removed 360 Amount of sediment _____

Miles of stream opened 0 Miles improved 35

Methods used hand labor and boom truck


Further action recommended follow up inspection

Location of maps and photos attached & U.S.G.S. Dutchmans Knoll 7-1/2

Additional comments, explanations, or details:

A large erosion causing jam formed on the South Fork of Ten Mile River in the winter of 1982-83. This jam was 100 feet wide x 120 feet long. This jam was well keyed into the banks and was floating at high water, but had the potential to become embedded.

CONFLUENCE
SOUTH
FORK
TEN MILE



4376
4375
4374
4373
123°45' 436 1510000 FEET 438 42°30' 410